(c) whether it is a fact that the power-points and tubelight points are not provided in the Government type-II quarters in New Delhi, particularly in Laxmibai Nagar; and

(d) if so, the reasons therefor and by when the power points and tubelight points will be provided in the locality?

THE MINISTER OF URBAN DEVELOPMENT (SHRI JAGMOHAN): (a) and (b) It is not true that wiring in Government quarters is in a bad shape. The wiring in respect of some quarters, whose construction is very old may have defects. Wherever wirings are found to be defective, they are replaced under "Special Repairs" funds to the extent of availability each year.

(c) and (d) Tube light and power points have not been provided in some type-II quarters, including Laxmibai Nagar since this was not as per norms when these quarters were constructed. These facilities can be provided at the specific request of the individual allottees on payment of 10% of the estimated cost as per rules.

Low water pressure in Vasant Vihar

81. SHRIMATI BASANTI SARMA: Will the MINISTER OF URBAN DEVELOPMENT be pleased to state:

(a) whether it is a fact that the water pressure in C.P.W.D. Colony, Vasant Vihar is very low;

(b) if so, the reasons therefor; and

(c) the action being taken or proposed to be taken by Government in this regard?

THE MINISTER OF URBAN DEVELOPMENT (SHRI JAGMOHAN): (a) Yes, Sir, Pressure in water supply mains of CPWD colony Vasant Vihar is generally low.

(b) Water in Vasant Vihar is supplied by Delhi Jal Board. Volume of water supplied by them is generally less than the required level.

(c) Government has asked Delhi Jal Board to augment water supply in Vasant Vihar. In addition, one more tube well has recently been sanctioned in the colony to augment water supply.